Maryland Historical Trust

Maryland Inventory of Historic Properties number: 4-5/9	
Name: CH-0016/Rock Point Rd over Wetstley	Fronz.
	0

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.

Eligibility	Recomn	nended _		RYLAND HISTORICAL TRUST Eligibility Not Recommended								
Criteria: _	A	B	c _	D Considerations: _	A _	В _	_c _	D _	E _	F _	GNc	one
Comments											W	
Reviewer, OPS:_Anne E. Bruder						Date:3 April 2001						
Reviewer, NR Program:Peter E. Kurtze						Date:3 April 2001						

Herm

MARYLAND INVENTORY OF HISTORIC PROPERTIES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION MARYLAND HISTORICAL TRUST

NAME AND SHA NO.: CH-0016

LOCATION Road Name and Number: Rock Point Road over Ditchley Prong City/Town: Wayside X vicinity Charles
Ownership: _ State X County _ Municipal _ Other
Bridge projects over: _ Road _ Railway X Water _ Land
Is bridge located within designated district?: _ yes X no NR listed district _ NR determined eligible district locally designated _ other Name of District _
BRIDGE TYPE
Timber Bridge Beam Bridge Truss-Covered Trestle Timber-and-Concrete
Stone Arch Bridge
Metal Truss Bridge
Moveable Bridge Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder Rolled Girder Rolled Girder Concrete Encased Plate Girder Plate Girder Concrete Encased
Metal Suspension
Metal Arch
Metal Cantilever
X Concrete Concrete Arch Concrete Slab X Concrete Beam Rigid Frame Other Type Name 397

MARYLAND INVENTORY OF HISTORIC PROPERTIES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION MARYLAND HISTORICAL TRUST

DESCRIPTION

Describe the Setting:

Situated in Maryland's Tidewater physiographic zone, Bridge CH-0016 carries Rock Point Road over Ditchley Prong near the village of Wayside in southeastern Charles County. Primarily rural in character with scattered dwellings and commercial establishments, Rock Point Road extends in a north-south direction while Ditchley Prong flows primarily in an easterly heading. A wooden worm fence borders the southeast approach to the bridge.

Describe the Superstructure and Substructure: (Discuss points identified in Context Addendum, Section C)

Composed of a single, concrete-beam span measuring 20-feet clear span, Bridge CH-0016 supports a 21½ foot clear roadway consisting of earth fill with a macadam wearing surface atop a concrete deck. The bridge is 23 feet long. Concrete parapets enframe the roadbed while concrete abutments and wing walls support the span.

Recent inspections of the bridge's condition have noted several spots of spall and scale on the underside of the slab. Some of the spalled areas exhibit exposed reinforcing bars. Bridge girders display a few minor spalls with portions of the reinforcing stirrups exposed. The concrete parapets feature light to medium scale and hairline cracks. The abutments possess light scale and some vertical and horizontal cracking.

A survey of historic concrete beam bridges undertaken by the Maryland State Highway Administration in the Fall of 1995 identified 113 bridges of that type located throughout the state. Slightly more than two-thirds (76) of that total were single-span bridges.

Discuss major alterations:

Inspection reports do not indicate that any major alterations have been undertaken.

HISTORY

When Built: 1920 Why Built: Unknown

Who Built: State Roads Commission

Who Designed: Unknown

Why Altered: Not applicable

398

MARYLAND INVENTORY OF HISTORIC PROPERTIES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION MARYLAND HISTORICAL TRUST

Was this bridge built as part of an organized bridge building campaign?: An examination of county records did not identify any relationship between construction of Bridge CH-0016 and organized building programs.

SURVEYOR ANALYSIS

This bridge may have NR significance for association with:

_ A (Events) _ B (Person) _ C (Engineering/Architectural Character)

Was this bridge constructed in response to significant events in Maryland or local history?

Research has not revealed any associations between the bridge and significant events contributing to Maryland and/or local history.

When the bridge was built, and/or given a major alteration, did it have a significant impact on the growth and development of the area?

Construction of Bridge CH-0016 does not appear to have had any significant impact on local development or growth.

Is the bridge located in an area which may be eligible for historic designation, and would the bridge add or detract from the historic and visual character of the possible district?

No, Bridge CH-0016 is not located in an area potentially eligible for historic designation.

Is the bridge a significant example of its type?

No, Bridge CH-0016 is not a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

Bridge CH-0016 appears to retain fair integrity of its character defining elements.

Date: 13 May 1996

Telephone: <u>(717)</u> 691-1340

MARYLAND INVENTORY OF HISTORIC PROPERTIES
HISTORIC BRIDGE INVENTORY
MARYLAND STATE HIGHWAY ADMINISTRATION
MARYLAND HISTORICAL TRUST

Is the bridge a significant example of the work of the manufacturer, designer, and/or engineer, and why?

County records do not identify the original construction authority, and therefore evaluating the bridge as a significant example of its manufacturer is problematic.

Should this bridge be given further study before significance analysis is made, and why?

Yes. Further study may identify the original construction body.

BIBLIOGRAPHY

Charles County Department of Public Facilities
Bridge Inspection Reports. On file at 1001 Radio Station Road, LaPlata, MD.

Spero, P.A.C., & Company, and Louis Berger & Associates, Inc.

1994 Historic Bridges in Maryland: Historic Context Report. Maryland State Highway
Administration, Baltimore.

State Roads Commission of Maryland
1958

A History of Road Building in Maryland. Baltimore.

SURVEYOR INFORMATION


Name:


Stuart Paul Dixon

Organization: Address:

KCI Technologies, Inc. 5001 Louise Dr., Suite 201

Mechanicsburg, PA 17055





CH-378 10F 4 BRIDGE # CH 16 CHORLES COUNTY D. BHAUMIK 2-2-95 MARYLAND SHPOSTA ROCK POINT ROAD OVER DITCHLEY PRONG LOOKING SOUTH ON RUCK POINT ROAD



2 of 4 CH-378 BRIDGE # CH 16 CHARLES COUNTY D. LOHAUMIK 2-2-95 MARY LOND SHPO SHA ROCK POINT ROAD OVER DITCHLEY PRONG LOOKING EAST (DOWN STREAM FACE)



3 OF 4 CH. 378 BRIDGE # CH 16 CHARLES COUNTY D. BHAUMIK 2-2-95 MARY LAND SHPO SHA ROCK POINT ROAD OVER DITCHLEY PRONG LOOKING NORTH ON ROCK POINT ROAD



4 OF 4 CH-378 BRIDGE # CH 16 CHARLES COUNTY D. BHAUMIK 2-2-95 SHPO SHA MARYLAND ROCK POINT ROAD OVER DITCHLEY PRING LOOKING WEST (UP STREAM FACE)